

**ROUB Certification Requirements****R1. GRADUATE OF A FORMAL TRAINING PROGRAM**

- Graduated from a CoA-OMP, CMA, or CAAHEP accredited program for OMP within 36 months prior to submitting your application.
  - If you have completed the program more than 36 months ago, you will need to obtain 25 approved credits for approved credit options.
- No work experience.

**R2. CURRENTLY CERTIFIED AS A COA, COT, COMT, or CDOS**

- Worked at least 2,000 hours (one year full-time) as a COA, COT, or COMT under an ophthalmologist or physician's supervision.

**R3. WORK EXPERIENCE**

- Worked at least 4,000 hours (two years full-time) as an Ultrasound Biometrist.
- Earned five hours of A-scan continuing education credits in a classroom setting.
- Earned one hour of A-scan continuing education credits in a hands-on course.

**Content Outline for the ROUB Examination**

Content Area		% of exam
1	Keratometry	5
2	Physics	16
3	Biometry Instrumentation	11
4	Instrument Settings for Biometry	13
5	Examination Techniques for Biometry	18
6	Sources of Error in Biometry	22
7	Intraocular Lens Power Calculations	15